

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOCRAPHS

HABS  
CONN  
8-WOOD,  
1-

Bowen House  
Woodstock  
Windham County  
Connecticut

HABS No. CT-376

Jack E. Boucher, Photographer, May 1970

- CT-367-1      GENERAL VIEW FROM ROAD
- CT-376-2      EXTERIOR, TYPICAL DORMER
- CT-376-3      EXTERIOR, FRONT PORCH, LEFT, SOUTHEAST
- CT-376-4      EXTERIOR, SOUTHEAST SIDE
- CT-376-5      EXTERIOR, SOUTHEAST SIDE, DETAIL DOOR
- CT-376-6      EXTERIOR, EAST FRONT
- CT-376-7      EXTERIOR, SOUTH FRONT
- CT-376-8      DETAIL DOORKNOB
- CT-376-9      DETAIL CATHEDRAL WINDOW
- CT-376-10     DETAIL OF TRACERY; QUATREFOIL MOTIF
- CT-376-11     INTERIOR, FRONT PARLOR LOOKING TO BACK PARLOR
- CT-376-12     INTERIOR FRONT PARLOR
- CT-376-13     INTERIOR, FRONT PARLOR
- CT-376-14     INTERIOR, FRONT PARLOR WITH BAY WINDOW
- CT-376-15     INTERIOR, FRONT PARLOR, EAGLE ORNAMENT OVER SLIDING DOORS
- CT-376-16     INTERIOR FRONT PARLOR MANTLE
- CT-376-17     INTERIOR GENERAL VIEW, BACK PARLOR
- CT-376-18     INTERIOR BACK PARLOR
- CT-376-19     INTERIOR BACK PARLOR FROM ARCHWAY
- CT-376-20     INTERIOR BACK PARLOR LOOKING TO FRONT PARLOR
- CT-376-21     INTERIOR KITCHEN
- CT-376-22     INTERIOR DINING ROOM SHOWING WINDOWS

CT-376-23	INTERIOR, DINING ROOM WITH MANTLE
CT-376-24	INTERIOR, DINING ROOM (CHINACLOSET)
CT-376-25	INTERIOR, DINING ROOM
CT-376-26	INTERIOR LANUDRY ROOM
CT-376-27	INTERIOR, CELLAR
CT-376-28	INTERIOR BOWLING ALLEY, FRONT END
CT-376-29	INTERIOR BOWLING ALLEY, REAR END
CT-376-30	INTERIOR FIRST FLOOW NORTHWEST CHAMBER
CT-376-31	INTERIOR FIRST FLOOW WEST END OF HALL CHAMBER
CT-376-32	INTERIOR DETAIL WALLPAPER, STAIRHALL FIRST FLOOR
CT-376-33	INTERIOR SECOND FLOOR, SMALL EAST CHAMBER
CT-376-34	INTERIOR SECOND FLOOR, CREEN CHAMBER
CT-376-35	INTERIOR SECOND FLOOR, NORTHEAST CHAMBER
CT-376-36	INTERIOR, SECOND FLOOR NORTHEAST CHAMBER
CT-376-37	INTERIOR SECOND FLOOR SORTHWEST CHAMBER
CT-376-38	INTERIOR SECOND FLOOR NORTHWEST CHAMBER
CT-376-39	INTERIOR, SECOND FLOOR SOUTHEAST GREEN CHAMBER
CT-376-40	INTERIOR SECOND FLOOR, SOUTHWEST "PRESIDENT'S CHAMBER"
CT-376-41	INTERIOR, SECOND FLOOR, SOUTHWEST "PRESIDENT'S CHAMBER"
CT-376-42	INTERIOR SOUTHWEST CHAMBER, SECOND FLOOR
CT-376-43	INTERIOR SECOND FLOOR, CENTER SOUTH CHAMBER IN WING
CT-376-44	INTERIOR SECOND FLOOR, CENTER NORTH CHAMBER IN WING
CT-376-45	INTERIOR SECOND FLOOR, BACK STAIR HALL
CT-376-46	INTERIOR SECOND FLOOR BACK STAIR HALL
CT-376-47	INTERIOR SECOND FLOOR ORIEL WINDOW
CT-376-48	INTERIOR SECOND FLOOR STAIR HALL
CT-376-49	INTERIOR SECOND FLOOR STAIR HALL

BOWEN HOUSE  
HABS No. CT-376 (Page 3)  
Index to Photographs

CT-376-50	INTERIOR NORTHWEST CHAMBER
CT-376-51	INTERIOR STAIR HALL
CT-376-52	INTERIOR STAIR HALL
CT-376-53	EXTERIOR, SHED
CT-376-54	EXTERIOR, CARRIAGE SHED